

Supplemental Type Certificate

Number ST02372LA

This Certificate issued to Super98 LLC
3780 Kilroy Way, Suite 430
Long Beach, CA 90806

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 and Part 26 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet A6WE and 26.11 (No wire interconnect systems affected) and 26.47 (No fracture critical structure created or affected)*

Original Product Type Certificate Number: A6WE

Make: Boeing

Model: DC-9-81, DC-9-82, DC-9-83, DC-9-87, MD-88

Description of Type Design Change: Installation of modifications to improve the airplane cruise performance in accordance with FAA approved Super98 LLC Master Drawing List AZZ0001, Revision "C" dated July 29, 2011 and FAA approved Super98 LLC Airplane Flight Manual Supplement RN-A13 Revision "A", dated September 14, 2011, or later FAA approved revisions. Accepted maintenance data applicable to this design change are available in Super98 LLC Instructions for Continued Airworthiness report RN-A08 Revision B, dated August 30, 2011.

Limitations and Conditions: The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 07, 2009


Date reissued:

Date of issuance: September 16, 2011

Date amended:



By direction of the Administrator



(Signature)

Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.